



REQUESTTRACKER

[VIEW SITE](#)

MAIN STATISTICS USERS

[TRY SEECLICKFIX](#)

[BACK](#)

Commissioner Comment/Request Form

IN PROGRESS #42

Category:	<input type="text" value="Commiss"/>	Last Modified: 6/15/2020	SUBMITTER	CONTACT	ADD COMMENT
Request Type:	<input type="text" value="Commiss"/>	Submitted: 6/15/2020	Ross Jenewein	rossta17@yahoo.com	PRINT WORK ORDER
Priority:	<input type="text" value="3 - Normal"/>	Source: Online Form	695 Dry Gulch Rd	4064655323	PRINT HISTORY
Assigned To:	<input type="text" value="Burrows,"/>	184.105.244.3	Stevensville, MT 59870		CLOSE REQUEST

CC Email List

You are using a browser that is not supported by the Google Maps JavaScript API. Consider changing your browser. [Learn more](#) [Dismiss](#)

[View larger](#)

Dry gulch Rd. Dry Gulch and Store Lane Intersection Stevensville, Montana 59870

Associated Requests

[ASSOCIATE](#)

REQUEST DETAILS

Description

Just would like dip in the road where a culvert was recently installed near the intersection of Store Lane and Dry Gulch Rd. to be filled with more dirt or preferably asphalt so its flush with the surface of the road. Right now there's probably a 4-5 inch difference in height now. Its been installed for prob 4-6 weeks now and only gets worse as time goes on. Its becoming dangerous for folks in cars mostly. If someone didn't know it was there (there's no signage indicating a bump ahead) and hit it going the speed limit it might mess up their alignment or something worse. If this could be remedied ASAP that would be greatly appreciated. Thank you..

[▶ Show Additional Details](#)

HISTORY TRAIL

Chris Taggart
6/16/2020 11:55 AM

[INSERT CANNED RESPONSE](#)

[SAVE & PUBLISH](#)

[SAVE](#)

This comment is only viewable internally

[Browse...](#)

Convert to PDF

For security reasons, anonymous users will not be sent attachment links or be able to view them.



HOMEPAGE



DASHBOARD



MODULES

