



Montana Department of Transportation

2701 Prospect
PO Box 201001
Helena MT 59620-1001

Greg Gianforte, Governor
Malcolm "Mack" Long, Director

December 20 2021

Ravalli County Commissioners
215 South 4th Street – Suite A
Hamilton, Mt 59840

RECEIVED

JAN 04 2022

Ravalli County Commissioners

--	--	--	--	--

Subject: 2021 Bridge Inspections

Attached are Bridge Inspection Reports for the following structures.

Please note listed below some of the structures have comments for recommended maintenance actions. Not all the structures listed will have recommended maintenance actions, as not all structures need attention.

- L41304099+08001 (04123) North Fork Burnt Creek
- L41053005+07001 (04107) Bear Creek
- L41700000+08001 (04133) West Fork Bitterroot River
- L41601014+01001 (04152) East Fork Bitterroot River
- L41653000+01001 (04163) East Fork Bitterroot River
- L41703003+05001 (04174) Rock Creek
- L41704000+03001 (04175) Rock Creek
- L41006003+08001 (04097) Big Creek
- L41006006+06001 (04098) Sweathouse Creek
- L41007000+06001 (04099) Mill Creek
- L41007004+00001 (04100) Fred Burr Creek
- L41007055+08001 (04101) South Bear Creek
- L41008002+00001 (04102) Blodgett Creek
- L41037001+03001 (04104) Kootenai Creek
- L41053002+01001 (04105) Mill Creek
- L41053002+03501 (04106) Fred Burr Creek
- L41053008+03001 (04108) Sweathouse Creek
- L41090000+07001 (04110) Mill Creek
- L41098000+06001 (04111) Blodgett Creek
- L41318001+04001 (04130) Surprise Ditch
- L41600005+01001 (04151) Sleeping Child Creek
- L41602009+00001 (04155) Sleeping Child Creek
- L41611000+02001 (04157) Sleeping Child Creek
- L41099000+03001 (04112) Mill Creek
- L41338001+01001 (04134) Sweeney Creek
- S00269020+08001 (06545) Bitterroot River Overflow; Recommended Maintenance:
Timber Decay * See Report

Kurt A Maart
Missoula District Bridge Inspection Manager
Montana Department of Transportation
2100 W Broadway PO BOX 7039
Missoula, MT 59807-7039
406-523-5825/ Cell 406-241-3817
Kmaart@mt.gov