

Missoula District Office  
2100 W Broadway  
PO Box 7039  
Missoula, MT 59807-7039

June 2, 2014

Ravalli County Commissioners  
215 South 4th Street - Suite A  
Hamilton, MT 59840

Subject: 2014 Inspection Cycle.

To Whom It May Concern,

Attached are Bridge Inspection Reports and Pictures for the following bridges.

Please note the addition of the Inspection Work Candidates section on page two. This section includes recommended maintenance actions. Not all reports include comments in this section, as not all structures need attention.

L41036004+05001 Bitterroot Canal  
L41053005+07001 Bear Creek  
L41077000+07661 Sweathouse Creek  
L41701000+01001 West Fork Bitterroot River  
L41304004+00001 Bitterroot Canal  
Recommended Maintenance: Repair spalled areas at girder rail post connections.  
L41304004+03001 North Burnt Fork Creek  
L41305000+01001 Supply Ditch  
L41382000+01001 Irrigation Canal  
L41394000+08001 Supply Ditch  
L41464000+03001 Bitterroot Canal

If you have any questions, please feel free to contact Jamie Shaw, the Missoula District Bridge Coordinator at (406) 523-5825 or 406 -471-0237.

*Daniel Reich*  
for  
Jamie Shaw  
Missoula District Bridge Coordinator

copies: Missoula District Bridge File  
Mike Murphy, Bridge Bureau/Bridge Management Section

RECEIVED

JUN 02 2014

Ravalli County Commissioners

--	--	--	--	--

*This is a large document. I have sent to RD Dept for their review. G.W.*