

Missoula District Office
2100 W Broadway
PO Box 7039
Missoula, MT 59807-7039

December 5, 2014

Ravalli County Commissioners
215 South 4th Street - Suite A
Hamilton, MT 59840

RECEIVED

DEC 12 2014

Ravalli County Commissioners

--	--	--	--	--

*I will
give to
RD Dept
g.w*

Subject: 2014 Inspection Cycle.

To Whom It May Concern,

Attached are Bridge Inspection Reports and Pictures for the following bridges.

Please note the addition of the Inspection Work Candidates section on page two. This section includes recommended maintenance actions. Not all reports include comments in this section, as not all structures need attention.

L41320000+06001 Skalkaho Creek Overflow
Recommended Maintenance: Patch large spall with exposed rebar on the bottom of the second beam from the left.
L41321002+05001 Skalkaho Creek
L41395001+09001 Irrigation Canal
L41423000+06001 Bitterroot Canal
L41463001+02001 Bitterroot Canal
L41500002+01001 Bitterroot Canal
L41505000+06001 Skalkaho Creek
L41608001+03001 Skalkaho Creek
S00373002+04001 Corvallis Canal
S00531003+04001 Sawtooth Creek

If you have any questions, please feel free to contact Jamie Shaw, the Missoula District Bridge Coordinator at (406) 523-5825 or 406 -471-0237.

Daniel Beis
be

Jamie Shaw
Missoula District Bridge Coordinator

copies: Missoula District Bridge File
Mike Murphy, Bridge Bureau/Bridge Management Section