

Missoula District Office
2100 W Broadway
PO Box 7039
Missoula, MT 59807-7039

March 16, 2015

Ravalli County Commissioners
215 South 4th Street - Suite A
Hamilton, MT 59840

RECEIVED

MAR 23 2015

Ravalli County Commissioners

--	--	--	--	--

Subject: 2014 & 2015 Inspection Cycle.

To Whom It May Concern,

Attached are Bridge Inspection Reports and Pictures for the following bridges.

Please note the addition of the Inspection Work Candidates section on page two. This section includes recommended maintenance actions. Not all reports include comments in this section, as not all structures need attention.

S00531001+06001 Roaring lion Creek
L41304009+08001 North Burnt Fork Creek
L41311001+02001 Supply Ditch
L41312003+02001 Supply Ditch
L41316000+06001 Surprise Ditch
L41320001+01001 Skalkaho Creek
L41404000+07001 Bitterroot River

Recommended Maintenance: Replace missing nuts on the transition rail at bent 5 - left.

L41404000+09001 Bitterroot River
L41404002+00001 Bitterroot River

Recommended Maintenance: Replace missing bolts in the rail; Re-anchor the right side wing wall at bent 1 on the right.

L41500000+07001 Bitterroot Canal

Recommended Maintenance: Repair spall with exposed rebar on the left exterior girder at bent 1 rail post; Repair spall with exposed rebar on the cap at bent 2.

L41511000+03001 Bitterroot Canal

Reports +
pics forwarded
to RD Dept
g.w

If you have any questions, please feel free to contact Jamie Shaw, the Missoula District Bridge Coordinator at (406) 523-5825 or 406 -471-0237.

Darnel Reub

for
Jamie Shaw

Missoula District Bridge Coordinator

copies: Missoula District Bridge File
Mike Murphy, Bridge Bureau/Bridge Management Section